

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633





Fig. 1



Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633







Fig. 2





Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633





Fig. 4



Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633






Fig. 5





Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633





Fig. 7

Fig. 7A

FIG. 9



Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633

FIG. 11b





Fig. 11a





Inventor: W. Lynn Benson
Serial No. 09/731,681
Attorney Docket No. T7082.CIP
Attorney: Vaughn W. North
(801) 566-6633




FIG. 12